



Information processing systems — Data communications — Use of the X.25 packet level protocol in local area networks

TECHNICAL CORRIGENDUM 1

Systèmes de traitement de l'information — Communication de données — Emploi du protocole X.25 au niveau paquet dans des réseaux locaux

RECTIFICATIF TECHNIQUE 1

Technical corrigendum 1 to International Standard ISO/IEC 8881:1989 was prepared by ISO/IEC JTC 1, *Information technology*.

Page 1

Subclause 3.3

Add the following:

- "e) DSAP
- f) SSAP"

Clause 4

Insert in alphabetical order the following:

"DSAP Destination Service Access Point
SSAP Source Service Access Point"

Page 2

Clause 5

Add a second paragraph as follows:

"The use of the X.25 PLP on a LAN shall be identified by setting the value of both the DSAP and SSAP addresses to "x111 1110"."

Pour plus d'infos, merci de nous contacter.

Association Sénégalaise de Normalisation

4 Avenue Jean Jaurès, Immeuble El Hadj Omar DIA, 6 ème Etage
Dakar - SENEGAL

Tel: +221 33 829 58 25

Email: asn@asn.sn